## REPORT OF CHANNEL CONDITIONS 400 FEET WIDE OR GREATER

(ER 1130-2-306)

PAGE 1 OF 1

DATE June 6, 2005

TO: The Record

**FROM:** U.S. Army Corps of Engineers

26 Federal Plaza, ATTN: CENAN-OP-ST

New York, NY 10278-0090

RIVER/HARBOR NAME AND STATE:

Gravesend Bay Anchorage

MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE	LEFT INSIDE	RIGHT INSIDE	RIGHT OUTSIDE
		WIDTH (feet)	LENGTH (nmiles)	<b>DEPTH</b> (feet)	QUARTER (feet)	QUARTER (feet)	QUARTER (feet)	QUARTER (feet)
Gravesend Bay Anchorage	Map 49, P 1, 21-22 March 2005	2250	1.1	47	49.8	47.4	45.8	44.8

## **REMARKS:**

- All depths in MLW
- Channel length is in nautical miles.
- Most of the anchorage is deeper than the project depth with the exception of the ends of the right half of the channel where minor shoaling has occurred.